


Evaluation Mobile Crusher		www.mevas.eu	
Customer:	<i>Rahman Al Bahar</i>	vers 12/11	
Machine / type:	<i>Parker RT16-6</i>		
Serial No.:	<i>045052088</i>	Hour reading:	<i>2957</i>
Inspector:	<i>Bühn</i>	Year:	<i>2007</i>
CE <input type="checkbox"/>	Primary Screen <input checked="" type="checkbox"/>	Jaw Crusher <input checked="" type="checkbox"/>	Impact Crusher <input type="checkbox"/>
Remote Control <input type="checkbox"/>	Magnetic Seperator <input checked="" type="checkbox"/>	Jaw Dimensions:	
engine		Serial No.	
leaks	<i>slight water leak</i>	noises	<i>normal</i>
oil condition	<i>change recommended</i>	blow by	<i>normal</i>
exhaust	<i>1 clam on turbo lose</i>	belts	<i>tightening required</i>
cooling system	<i>good</i>	air filter	<i>good</i>
visual inspection exterior		sheet metal	<i>good, slight dents</i>
engine hood	<i>good</i>	conveyor frames	<i>good</i>
steps, hand rails	<i>good</i>	conveyor belts	<i>good, got repairs</i>
catwalks	<i>good</i>	ripper walls	<i>good, a bit bent</i>
paintwork	<i>fair</i>	chassis	<i>good</i>
hydraulics		hydraulic cylinders	<i>1)</i>
hoses & lines	<i>some are leak</i>	coveyor motors	<i>good</i>
controls & valves	<i>good, 1 lever missing</i>	vibrators	<i>good</i>
functional test		crusher adjustment	<i>working</i>
conveyors	<i>good</i>	drive train	<i>working</i>
magnetic seperator	<i>good</i>	conveyor folders	<i>good</i>
feeder hopper	<i>good</i>	braker clutch	<i>good</i>
jaw crusher			
toggle & mechanic	<i>good, some visible wear</i>	cracks	<i>none</i>
jaw wear	<i>70% worn</i>	jaw liner wear	<i>fair condition</i>
wear measurement			
impact crusher			
impactor wear		cracks	
side liners wear		belts	
Feeder		springs	<i>good</i>
walls & liners	<i>liners worn</i>	wear	
grizzly fingers	<i>please re-inforce</i>	cracks	<i>none</i>
Undercarriage		remaining life	<i>70%</i>
operates fwd	<i>yes</i>	operates reverse	<i>yes</i>
track shoe width	<i>600</i>	rollers	<i>no</i>
Safety Items		emergency switches	<i>OK</i>
crusher protection		platform railings	<i>good</i>
problems, details			
<i>1) toggle cylinder bearings broken, cylinder is leaking (seller has ordered a new one already)</i>			
<i>Track tension on undercarriage to be adjusted.</i>			
<i>General comment: The crusher is in good operating condition. Some visible wear in feeder, grizzly and jaw. Feeder should be re-inforced and grizzly as well.</i>			
<i>Engine and hydraulics are in good condition. Just some slight leaks to be sealed.</i>			
<i>Conveyor belts got some repairs and should be watched in work process.</i>			
dimensions for transport L x W x H in meter:			



Seite 1 von 2

[Weiter »](#)

Pictures 1-20 of 38