


Evaluation Asphalt Paver		<a href="http://www.mevas.eu">www.mevas.eu</a>	
customer	Rüko	vers 10/12	
inspector:	11		
machine / type:	Vögele 1800-1	year:	
Serial No.:	07820212	hour reading:	6972
CE <input checked="" type="checkbox"/>	Canopy <input checked="" type="checkbox"/>	Extension box's <input type="checkbox"/>	Compaction type <input checked="" type="checkbox"/>
Screed Heating system <input checked="" type="checkbox"/>		Screed width:	
<b>cab / canopy</b>			
seat	<i>cushion is damaged</i>	lights	<i>good</i>
switches	<i>good</i>	bacons	
gauges	<i>good</i>	steps	<i>good</i>
canopy	<i>good</i>	grab irons	<i>good</i>
<b>engine</b>			
leaks	<i>change recommended</i>	blow bye	<i>good</i>
oil condition	<i>change recommended</i>	belts	<i>good</i>
exhaust	<i>slight dents</i>	batteries	<i>good</i>
smoke	<i>normal</i>	heater	<i>not tested</i>
<b>visual inspection</b>			
chassis	<i>good</i>	auger	<i>good</i>
covers/doors	<i>good</i>	screed	<i>good</i>
engine hood	<i>good</i>	conveyer	<i>good</i>
axles	<i>good</i>	hopper	<i>good</i>
paintwork	<i>good</i>		
<b>hydraulics</b>			
hose lines	<i>good</i>	cylinders	<i>good</i>
pumps	<i>good</i>	oil level/condition	<i>good</i>
		drive motors	<i>good</i>
<b>functional test</b>			
	comments		
auger	<i>working</i>		
conveyer drive	<i>working</i>		
transmission fwd	<i>1)</i>		
transmission reverse	<i>1)</i>		
park brake	<i>good</i>		
sensors	<i>manual adjust, ok</i>		
steering	<i>good</i>		
<b>tires/ UC</b>	<b>% remaining</b>	<b>size / brand</b>	<b>cuts</b>
chaines	<i>70</i>		
idler	<i>70</i>		
rollers	<i>70</i>		<i>maybe some are leak</i>
sprockets	<i>70</i>		
shoes	<i>50</i>		
<b>problems, repairs, recommendation</b>			
<i>Engine was hard to start. There was a problem in the fuel system.</i>			
<i>1) the drive train was working in one speed. But suddenly it did not work anymore.</i>			
<i>After MEVAS inspection the supplier has fixed the engine fuel problem and sorted out the drive train problem.</i>			
<i><a href="https://www.youtube.com/watch?v=C9FvD...">https://www.youtube.com/watch?v=C9FvD...</a></i>			
<i>Generally the machine is in working order. Screed, bunker, augers and conveyors were presented in working mode. Both remote controls work.</i>			
<i>Undercarriage parts are partially caked with asphalt residues.</i>			
dimension for transport L x W x H in meter:			

Sample Report

Sample Report



IMGP7621.JPG



IMGP7622.JPG



IMGP7623.JPG



IMGP7625.JPG



IMGP7626.JPG



IMGP7627.JPG



IMGP7629.JPG



IMGP7630.JPG



IMGP7631.JPG



IMGP7632.JPG



IMGP7633.JPG



IMGP7634.JPG



IMGP7636.JPG



IMGP7637.JPG



IMGP7638.JPG



IMGP7639.JPG



IMGP7640.JPG



IMGP7641.JPG



IMGP7643.JPG



IMGP7644.JPG



IMGP7645.JPG



IMGP7646.JPG



IMGP7647.JPG



IMGP7648.JPG

The original report comes with approximately 40-50 pictures

Videos can be done on demand

Get in touch with Mevas for an inspection quotation

More details about heavy machinery inspections you can find at

[www.mevas.eu](http://www.mevas.eu)

We are your partner in Europe for inspections of used heavy equipment such as excavators, motor-graders, cranes, bulldozers, concrete pumps and rock drills.