

Evaluation Motor Grader		www.mevas.eu		
customer/location:	<i>Tanka, France</i>	vers 12/11		
machine / type:	<i>140G</i>			
Serial No.:	<i>72V192X</i>	hour reading:	<i>1735</i>	
inspector:	<i>Bühn</i>	year:		
CE: <input type="checkbox"/>	AWD <input type="checkbox"/> Suppl. steer <input type="checkbox"/>	push bloc <input type="checkbox"/>	snow wing <input type="checkbox"/>	ripper <input checked="" type="checkbox"/>
A/C <input type="checkbox"/>	Parts book <input type="checkbox"/>	Op-Manual <input type="checkbox"/>	scarifier <input type="checkbox"/>	ripper-valve <input checked="" type="checkbox"/>
cab		controls	<i>good</i>	
seat	<i>good</i>	windows	<i>front window has a crack</i>	
switches	<i>good</i>	wipers	<i>not working</i>	
gauges	<i>good</i>	stairs/grab iron	<i>stairs OK but not original</i>	
A/C / heater	<i>N/A</i>	floor mat	<i>good</i>	
engine		Serial No.		
leaks	<i>fuel leak, oil residues</i>	air filter	<i>good</i>	
oil condition	<i>new</i>	noises	<i>normal</i>	
exhaust	<i>good</i>	blow by	<i>normal</i>	
smoke	<i>normal</i>	belts	<i>good</i>	
cooling system	<i>good</i>	fluid levels	<i>coolant is low</i>	
visual inspection		paintwork	<i>good, a bit faded</i>	
frames	<i>good</i>	lights	<i>good, not al working</i>	
cab structure	<i>good</i>	engine doors	<i>N/A</i>	
center blade	<i>good, wear in side shift slides</i>	sheet metal	<i>good</i>	
front blade	<i>N/A</i>	rims	<i>good</i>	
circle drive	<i>good</i>	tandems	<i>good</i>	
hydraulics		pumps	<i>good</i>	
hoses & lines	<i>some slight leaks</i>	steering cyl.	<i>leak, one has damages</i>	
circle drive	<i>working</i>	blade cylinders	<i>good</i>	
controls in cab	<i>good</i>	ripper cylinders	<i>good but leak</i>	
functional test		blade pins	<i>some play noted</i>	
transmission auto	<i>N/A</i>	blade side shift	<i>working, some play noted</i>	
transmission man.	<i>good</i>	circle play	<i>still OK</i>	
brake/ park brake	<i>a bit weak</i>	front blade	<i>N/A</i>	
steering	<i>good</i>	ripper / scar.	<i>all teeth missing</i>	
wheel lean	<i>good</i>	suppl. steering	<i>N/A</i>	
electric system	<i>need new batteries</i>	power test	<i>sufficient</i>	
tires	tread in mm or % remaining	size & brand	cuts	remould
front right	<i>20</i>	<i>?</i>	<input type="checkbox"/>	<input type="checkbox"/>
front left	<i>20</i>	<i>?</i>	<input type="checkbox"/>	<input type="checkbox"/>
center right	<i>60</i>	<i>Bridgestone</i>	<input type="checkbox"/>	<input type="checkbox"/>
center left	<i>60</i>	<i>Bridgestone</i>	<input type="checkbox"/>	<input type="checkbox"/>
rear right	<i>60</i>	<i>Bridgestone</i>	<input type="checkbox"/>	<input type="checkbox"/>
rear left	<i>60</i>	<i>Bridgestone</i>	<input type="checkbox"/>	<input type="checkbox"/>
problems, repairs, recommendation				
<i>Rear and center tires are good, front tires are fair.</i>				
<i>Machine is in working condition. Engine power is still OK. Transmission is shifting all gears.</i>				
<i>Brakes seem a bit weak. Injection pump is leaking fuel, slight oil leak on RHS of engine.</i>				
<i>More or less all hydraulic cylinders are leaking. Some have slight damages on chrome.</i>				
<i>Estimated total frame hours are 12.000-15.000, maybe even more.</i>				
http://www.mevas.ru				
http://www.mevas.fr				

