<b>Evaluation Articulate</b>	ed Dump Truck	www.mevas.eu	(8)						
Customer/location: Chepstow International		vers 10/12							
Inspector:	Mevas Inspector 2								
Machine / type:	Cat 730	Hour reading:	7068						
Serial No. :	B1M00302	Year:							
CE 🗸	air conditioner	auto lube 🗹	retarder 🗸						
tailgate 🗸	exhaust heat 🗸	sup.steer 🗸	Manual 🗸 Parts book 🗍						
cab	good	cab door	good						
seat	good but L/H Arm rest missing	windows	good						
switches	good except Heater coontrol	wipers	good						
gauges	good	floor mats	good						
aircon / heat	See comments	structure	good						
engine	See comments	Serial No.							
leaks	Navisible from below_	noises	Started and Pan well						
oil condition									
			e externally						
smoke	good	fluid levels	Coolant ok						
cooling system	good	power	good						
exterior		cooler grills	good						
chassis	good	bumpers/fenders	good						
engine hood	would not lift	lights	good						
stairs, hand rails	good	paintwork	good, some rust spots						
power train		rims	good						
axles	good	universal joints	good 1)						
transmission	good	brake disk	good						
hydraulics	good	steering cylinders	good, very slight play						
hoses & lines	good	pumps	good						
lift cylinders	Minor play Top and Bottom pins	steering orbital	good						
functional test	Inmier play 1 op and Bettern pine	steering	good,						
stall test	2)	articulation play	good						
transmission fwd.	good	body lift	good						
transmission rev.	good	electrics	good						
service break	good	park brake	good						
truck body	9000	pins	New Pins but Bosses Skip Worn 3)						
welds	good	tail gate	good						
bed condition	Good	side wall condition	good.Small Dents on L/H Side						
tires		23.5 X 25							
	mm or % good 18 mm 10%		cuts recapped Ser. No.						
front right	18mm 10%	Bridgstone	☐ F5R381034						
front left		Bridgstone	☐ F5R381751						
center right	9mm 5% 13mm 7%	Bridgstone Michelin	□ □ F5R3812908 □ □ VVC0470V1A						
center left	4mm Poor	Bridgstone	□ □ VVC0470V1A □ □ F6K282265						
rear right			VVC0462V9A						
rear left problems, details			ature and heater						
	and not adjustable, Engine hood								
	n from below; 1) slight play in S		·						
			out Shart						
2) Drive test was performed and all gears change well. Brakes react good.									
Picture 2330 shows a broken hose on the center axle but we believe it is just a breather for axle.									
A bit play noted in steering and lift cylinders but it is appropriate to hour level and not a problem so far.  3) The wear in the Pin Bosses on the Body mounting Pins will soon require Line Bore and Bushing									
There are logged service codes: E267 (2) Engine shut down switch erratic/incorrect									
There are rogged service codes. L207 (2) Engine shut down switch enductinconect									
dimensions for transp	ort L x W x H in meter:	10mtrX2.8mtrX3.75							
יייייייייייייייייייייייייייייייייייייי	VOIL E X VV X I I III III ELEI.	1011111/2.011111/0.70							

r		1		,		•		
	IMGP2287,J PG	IMGP2288.J PG	IMGP2290.J PG	IMGP2292.J PG	IMGP2293.J PG	IMGP2294.J PG	IMGP2296.J PG	
	IMGP2297.J PG	IMGP2298.J PG	IMGP2300.J PG	IMGP2301.J PG	IMGP2303.J PG	IMGP2305.J PG	IMGP2306.J	
	IMGP2307.J	IMGP2308,J PG	IMGP2309.J PG	IMGP2310.J PG	IMGP2311.J PG	IMGP2312.J PG	IMGP2313.J PG	
	IMGP2314.J PG	IMGP2316.J	IMGP2318.J PG	IMGP2319.J	IMGP2320.J	IMGP2322.J PG	IMGP2325.J PG	
	IMGP2326.J PG	IMGP2327,J PG	IMGP2330.J PG	IMGP2331.J PG	IMGP2332.J PG	IMGP2335.J PG	IMGP2337.J — PG	
	IMGP2338.J PG	IMGP2340.J	IMGP2342,J PG					
		comes with ap	proximately 4	0-50 picture	S			
Viacoc	Videos can be done on demand							
Get in	touch with Me	evas for an ins	spection quoa	tation				
More o	letails ahout l	neavy machin	ery inspection	s vou can fir	nd at			
More details about heavy machinery inspections you can www.mevas.eu								
					y equipment somes and rock of			
CACCAVE	ators, motor g	radors, crario	o, buildozero,	concrete pu	inpo ana rook (	armo.		