

























Evaluation Bull Dozer		www.mevas.eu	
Customer:		version 01/14	
Date:	14.01.2015		
Machine / type:	CAT D6R	location:	Russia, St-Petersburg
Serial No.:	S6X01138	Hour reading:	3026,9
Inspector:		Year:	2012
CE <input type="checkbox"/>	A/C <input checked="" type="checkbox"/>	ripper <input checked="" type="checkbox"/>	LGP <input type="checkbox"/>
laser control <input type="checkbox"/>	ripper valve <input type="checkbox"/>	Op-Manual <input type="checkbox"/>	Parts book <input type="checkbox"/>
cab		cab doors	good
seat	good	windows	good
switches	good	wipers	good
gauges	good	floor mats	good
aircon / heat	good	struct	good
engine		serial	
leaks	good	smok	no
oil condition	good	blow by	minor
exhaust	good	belts	good
cooling system	good	fluid levels	coolant level low
exterior visual insp.		sheets and doors	minor dents
push frame	good	tanks	minor dents
engine hood	good	lights	good
steps, hand rails	minor dents	paintwork	minor scratches
hydraulics		tilt cylinder	good
hoses & lines	good	angle cylinder	good
lift cylinders	good	ripper cylinder	none
functional test / play localization			
pins push frame	good	pump noises	none
pins blade	good	electrics	good
pins ripper	good	transmission	good
equalizer bar	good	brakes / clutches	good/good
stall test	2100-->1600 RPM	steering	good
blade	SU <input checked="" type="radio"/> S <input type="radio"/> U <input type="radio"/> PAT <input type="radio"/>		
front condition	good	base (ground edge)	3260 mm
edge condition	80% remaining	spill rack	good
U/C	Right side % good	Left % good	track shoe width in mm:
bushings	50	50	590 mm
shoes	40	40	rotating bushings <input type="checkbox"/>
idler front	50	50	
idler rear	60	60	CAT System One <input type="checkbox"/>
carrier roller	none	none	part No. track links:
links	60	60	
sprockets	50	50	part No. rollers
rollers	50	50	
canon condition	good	good	
problems, details	probably no EPA		
Tanks and fender RHS slightly bent upwards.			
Limited under carriage evaluation due to Sealed & lubricated track chains only but no rotating bushings			
Ripper has been disassembled.			
Machine in general good condition. Scheduled maintenance recommended.			
dimensions for transport L x W x H in meter:		5,1x3,3x3,2	

Sample Report

Sample Report

					
D6R (8).JPG	D6R (9).JPG	D6R (10).JPG	D6R (11).JPG	D6R (12).JPG	D6R (13).JPG
					
D6R (15).JPG	D6R (16).JPG	D6R (17).JPG	D6R (18).JPG	D6R (19).JPG	D6R (20).JPG
					
D6R (22).JPG	D6R (23).JPG	D6R (24).JPG	D6R (25).JPG	D6R (26).JPG	D6R (27).JPG
					
D6R (29).JPG	D6R (30).JPG	D6R (31).JPG	D6R (32).JPG	D6R (33).JPG	D6R (34).JPG
The original report comes with approximately 40-50 pictures					
Videos can be done on demand					
Get in touch with Mevas for an inspection quotation					
More details about heavy machinery inspections you can find at					
www.mevas.eu					
We are your partner in Europe for inspections of used heavy equipment such as excavators, motor-graders, cranes, bulldozers, concrete pumps and rock drills.					