


Evaluation Road Truck		www.mevas.eu			
Date:	13. Mrz	vers 12/11			
Brand/type	DB Actros 3340				
chassis No.:	65703			km reading	505551
Inspector:	Andreas			Year:	2006
	retarder <input checked="" type="checkbox"/>			air condition	<input checked="" type="checkbox"/>
cab		cab doors	good		
seat	good	windows	good		
switches	good	wipers	good		
gauges	good	floor mats	good		
aircon / heat	A/C not operable	passenger seat	good		
engine	OM 501 LA	Serial No.	115931		
leaks	rocker cover	noises	good		
oil condition	change due	blow by	good		
exhaust	good	belts	good		
cooling system	good	power	good		
exterior		doors	good		
frames	good	bumpers	good		
sheet metal	good	lights	see details		
stairs, hand rails	good	paintwork	good		
power train					
axles	2nd axle leak	universal joints	good		
gearbox	good	differentials	good		
transmission gear	good	brake drums/ disk	good		
hydraulics/ pneumatics		brake accumulators	good		
hoses & lines	1 has a leak	hydraulic pump	good (cab)		
steering cylinders	good	compressor	good		
lift cylinders	Good (cab)	steering pilot	good		
functional test					
mixer		steering	good		
transmission fwd.	good	transmission rev.	good		
brakes	good	park brake	good		
mixer		drum drive			
drum condition outside		drum rollers			
drum condition inside		chutes			
tires		right	left		
axle 1		7 mm	7 mm		
axle 2		315/80 22.5			
axle 3 inside		0 mm	0 mm		
axle 3 outside		3 mm	0mm		
axle 4 inside		0 mm	3 mm		
axle 4 outside		4 mm	4 mm		
problems, repairs, recommendation					
Wiper are too slow.					
Engine has a slight leak on valve cover					
Pressure 1st brake circuit is not sufficient					
Hose to oil cooler servo leaks, Exchanger not in good condition missing (system empty)					
Cardan seal 2nd axle leak.					
Batteries should be changed, jump start required. Front lights are dull.					
Is the appearance of the truck according to the km-reading yes <input checked="" type="radio"/> no <input type="radio"/>					
dimension for transport (L x W x H) Meter					

page 1 of 1		chassis number:	65803
additional features			
unit has DB AP axles			
brand			
transmission	ZF G240 – 16	S/N	100955
rear gearbox		S/N	
mixer		S/N	
mixer pump		S/N	
mixer drive			
additional comments:			
<i>The truck is in fair condition. Some service and smaller repairs are required. Cab is quite dirty inside.</i>			

