



























Evaluation Wheel Loader		www.mevas.eu		
Customer:	APN		vers 10/12	
Date:	23.06.2014			
Machine / type:	Komatsu WA 470-6	location:		
Serial No.:	KMTWA098L79H50626	Hour reading:	6773,5 Bh	
Inspector:	JK	Year:	2008	
CE <input checked="" type="checkbox"/> A/C <input checked="" type="checkbox"/>	Command Steer <input type="checkbox"/>	auto lube <input checked="" type="checkbox"/>	3rd valve <input type="checkbox"/>	
coupler <input type="checkbox"/>	sup.steer <input type="checkbox"/>	weigh load <input type="checkbox"/>	Parts book <input type="checkbox"/> Op-Manual <input type="checkbox"/>	
cab		cab door	good	
seat	seat console is shaky (2)	windows	mirror on the back is cracked	
switches	(1)	wipers	blades are broken	
gauges	good	floor mats	good	
aircon / heat	fans are noisy	structure	some bolts missing on covers	
engine		Serial No.		
leaks	breather is a bit oily	cooling system	good	
oil condition	oil on ground from the oil dip	oil by	normal	
exhaust	leaks on particulate filter (1)	bolts	some need to crack	
smoke	good	fluid levels	good	
exterior		counterweight	good	
chassis	good	fenders	slight dents	
engine hood	(4)	lights	good	
stairs, hand rails	bent on both sides	paintwork	scratched and rusty	
power train		rims	good	
axles	seepage on the back	universal joints	good	
gearbox	good	differentials	good	
power train	good	transm. noises	good	
hydraulics		steering cylinders	some play in pins	
hoses & lines	hose to cooler leaks	pumps	good	
lift & tilt cylinders	good	steering orbital	good	
functional test		full bucket lift in seconds:		
steering	rough on joystick	articulation play	some play	
transmission test	good	loader pins	some play	
stall test	1850 rpm	electric system	batteries are broken	
brake / park brake	good	supplem. steering	good	
bucket	25% remaining	width / capacity	3m	
edges / teeth	worn	sides	worn	
bottom	(5)	coupler		
tires	mm or % good	Size: 26,5-R25	cuts recapped Serial No.	
front right	30 mm	brand: Tubless	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
front left	30 mm	brand: Tubless	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
rear right	2 mm	brand: Michelin	<input checked="" type="checkbox"/>	<input type="checkbox"/>
rear left	2 mm	brand: Michelin	<input checked="" type="checkbox"/>	<input type="checkbox"/>
problems, details:				
	(1) The direction switch is not working on the joystick.			
	(2) The seat console is shaky and needs to be fixed.			
	(3) heat guard on front of S... is damaged.			
	(4) noise reduction pads are damaged, rubber seals and gas struts are broken on both sides			
	(5) The bucket is cracked and wear plates are worn through and bucket stops are dent.			
	The transmission guard is bent slightly. Seepage on transmission.			
	The machine is in general good condition. Some small repairs and replacements are required.			
transport dimensions L x W x H in meter:	8,05 X 3,0 X 3,50			

				
SAM_1544.JPG	SAM_1545.JPG	SAM_1546.JPG	SAM_1547.JPG	SAM_1548.JPG
				
SAM_1551.JPG	SAM_1552.JPG	SAM_1553.JPG	SAM_1554.JPG	SAM_1555.JPG
				
SAM_1559.JPG	SAM_1560.JPG	SAM_1561.JPG	SAM_1562.JPG	SAM_1563.JPG
				
SAM_1566.JPG	SAM_1567.JPG	SAM_1568.JPG	SAM_1569.JPG	SAM_1570.JPG
				
SAM_1573.JPG	SAM_1575.jpg	SAM_1576.JPG	SAM_1577.JPG	SAM_1578.JPG
The original report comes with approximately 40-50 pictures				
Videos can be done on demand				
Get in touch with Mevas for an inspection quotation				
More details about heavy machinery inspections you can find at				
www.mevas.eu				
We are your partner in Europe for inspections of used heavy equipment such as excavators, motor-graders, cranes, bulldozers, concrete pumps and rock drills.				