


Evaluation Wheel Loader		www.mevas.eu	
Customer:	<i>Heinz Harald</i>	vers 05/11	
Date:	<i>03.04.2011</i>		
Machine / type:	<i>Deawoo Mega 300</i>		
Serial No.:	<i>1212596</i>	Hour reading:	<i>2197</i>
Inspector:	<i>Buehn</i>	Year:	<i>20</i>
CE <input checked="" type="checkbox"/>	air con. <input checked="" type="checkbox"/>	auto lube <input checked="" type="checkbox"/>	oil valve <input checked="" type="checkbox"/>
coupler <input checked="" type="checkbox"/>	sup.steer <input type="checkbox"/>	weigh load <input type="checkbox"/>	Parts book <input type="checkbox"/> Op-Manual <input checked="" type="checkbox"/>
cab	<i>dashboard melted</i>	cab door	<i>good</i>
seat	<i>good but dirty</i>	windows	<i>good</i>
switches	<i>good</i>	wiper	<i>rear is not working</i>
gauges	<i>good</i>	floor mats	<i>good</i>
aircon / heat	<i>good but cab air filter dirty</i>	structure	<i>good</i>
engine		Serial No.	<i>0120815</i>
leaks	<i>residue on fuel pump</i>	cooling system	<i>good</i>
oil condition	<i>good</i>	blow by	<i>moderate blow by</i>
exhaust	<i>good</i>	belts	<i>need adjustment</i>
smoke	<i>good</i>	fluid levels	<i>transmission oil a bit low</i>
exterior		counterweight	<i>good</i>
chassis	<i>good</i>	fenders	<i>hard to open due bent hinges</i>
engine hood	<i>good</i>	lights	<i>good</i>
stairs, hand rails	<i>minor dents</i>	paintwork	<i>has been repainted recently</i>
power train		rims	<i>good</i>
axles	<i>good</i>	universal joints	<i>good</i>
gearbox	<i>good</i>	differentials	<i>good</i>
power train	<i>good</i>	transm. noises	<i>good</i>
hydraulics		steering cylinder	<i>some play in pins</i>
hoses & lines	<i>hose on steering pilot leaks</i>	pumps	<i>good</i>
lift & tilt cylinders	<i>LHS lift cylinder leaks</i>	steering pilot	<i>good</i>
functional test		full bucket lift (records):	<i>empty bucket 6.1sec</i>
steering	<i>good</i>	articulation play	<i>minor play</i>
transmission test	<i>limited tested up to 3rd gear</i>	loader pins	<i>some play in bucket pins</i>
stall test	<i>2100->1600RPM good</i>	electric system	<i>good</i>
brake / park brake	<i>good/good</i>	supplem. steering	
bucket		width / capacity	<i>2.92m</i>
edges / teeth	<i>edges good/teeth worn</i>	sides	<i>good</i>
bottom	<i>good</i>	coupler	<i>hydraulic coupler</i>
tires	mm tread good	<i>23.5R25</i>	cuts recapped Serial No.
front right	<i>27mm</i>	<i>Michelin XADN</i>	<input type="checkbox"/> <input type="checkbox"/>
front left	<i>27mm</i>	<i>Michelin XADN</i>	<input type="checkbox"/> <input type="checkbox"/>
rear right	<i>27mm</i>	<i>Michelin XADN</i>	<input type="checkbox"/> <input type="checkbox"/>
rear left	<i>27mm</i>	<i>Michelin XADN</i>	<input type="checkbox"/> <input type="checkbox"/>
problems, details	<i>The machine is in good condition.</i>		
	<i>Scheduled maintenance and some cosmetic repairs are recommended but not necessary.</i>		
transport dimensions L x W x H in meter:	<i>8.1m x W 2.95m x H 3.5m</i>		



Seite 1 von 2

[Weiter »](#)