


Evaluation Tracked Excavator		<a href="http://www.mevas.eu">www.mevas.eu</a>	
Customer:	<i>Johnny Johnson</i>	vers 12/10	
Date:	<i>16.05.2011</i>		
Machine / type:	<i>325CLN</i>	Hour reading:	<i>8135,2</i>
Serial No.:	<i>CRB160511</i>	Year:	<i>2003</i>
Inspector:	<i>Buehn</i>	stick length:	<i>2.5m</i>
CE <input type="checkbox"/>	air con <input checked="" type="checkbox"/>	boom check valve <input checked="" type="checkbox"/>	
auto lube <input type="checkbox"/>	stick check valve <input checked="" type="checkbox"/>	boom variable <input type="checkbox"/>	parts book <input checked="" type="checkbox"/> Op-Manual <input checked="" type="checkbox"/>
blade <input type="checkbox"/>	auxiliary lines <input type="checkbox"/>	quick coupler type	
<b>cab</b>		cab door	<i>good</i>
seat	<i>good</i>	windows	<i>Windscreen is cracked</i>
switches	<i>good</i>	wipers	<i>Wiper blade is worn</i>
gauges	<i>SMU is cracked</i>	fluorescence	<i>OK</i>
aircon / heat	<i>not cooling down / good</i>	temperature	<i>ROPS appear good</i>
<b>engine</b>		fluid levels	<i>coolant a bit low</i>
leaks	<i>none seen</i>	noises	<i>good</i>
oil condition	<i>change recommended</i>	blow by	<i>above the average</i>
exhaust	<i>good</i>	belts	<i>good</i>
smoke	<i>black smoke on start up</i>	cooling system	<i>good</i>
<b>visual inspection exterior</b>		covers	<i>some dents on corners</i>
chassis	<i>good</i>	side doors	<i>several dents</i>
engine hood	<i>minor dents</i>	compartments	<i>clean</i>
steps, hand rails	<i>dent step on RHS</i>	bumpers / catwalk	<i>RHS has minor dents</i>
boom	<i>good</i>	lights	<i>boom light is missing</i>
stick	<i>good</i>	paintwork	<i>scratched and chipped</i>
<b>hydraulics</b>		boom cylinders	<i>good</i>
hoses & lines	<i>good</i>	stick cylinder	<i>good</i>
pump and valve block	<i>good</i>	bucket cylinder	<i>scratches on rod surface</i>
<b>functional test</b>		boom drift	<i>none</i>
pins boom	<i>moderate play</i>	pump noises	<i>good</i>
pins stick	<i>good</i>	slew ring play	<i>good</i>
pins bucket	<i>ample play</i>	electrics	<i>good</i>
swing drive/brake	<i>good</i>	drive train	<i>slightly bent frame</i>
<b>tools</b>		bucket 2	<i>none</i>
bucket 1	<i>1.6m</i>	condition	
condition	<i>worn and welded segments</i>	coupler condition	<i>none</i>
<b>U/C</b>	<b>remaining life %</b>		<b>remaining life %</b>
bushings	<i>70-80%</i>	track links	<i>75%</i>
shoes	<i>60%</i>	sprockets	<i>70%</i>
idlers	<i>70%</i>	rollers	<i>60%</i>
carrier rollers	<i>75%</i>	shoe width in mm:	<i>600mm</i>
<b>problems, details</b>	<p><i>The machine is in good to fair condition. Scheduled maintenance and several repairs are required. Hours and condition are reasonable. Machine was frequently serviced by the local dealer. Undercarriage is in good condition. Bucket need to be replaced soon.</i></p> <p><i>Machine has lines for hammer &amp; grapple. Books are available in German language only.</i></p>		
dimensions for transport L x W x H in meter:	<i>9.8m x 3m x 3.45m</i>		



[« Vorherige](#)

Seite 2 von 3

[Weiter »](#)